

Material Safety Data Sheet

Identity		T2131 / T2141 / T2151 / TX4511 / TX5511 TX1511 / TX2511 / TX6511 / TX6311	
UB5322001			
SECTION I			
Manufacturer's Name		Emergency Telephone Number	
Fuji Kagakushi Kogyo Company Limited		(06) 471-7071	
Address		Telephone Number for Information	
8-43, Utajima 4-chome, Nishi Yodogawa-ku, Osaka 555, Japan		(06) 471-7071	
		Date Prepared	
		Dec. 16, 1991	
SECTION II - Hazardous Ingredients/Identity Information			
Hazardous Components	CAS No.	OSHA PEL	ACGIH TLV Other Limits
Paraffin Wax (fume)	8002-74-2	N/A	2.0mg/m ³ N/A
Carbon Black	1333-86-4	3.5mg/m ³	3.5mg/m ³ N/A
Predominant Components	Not Applicable		
Coloring material			
Wax			
Resin			
Additive			
Polyethyleneterephthalate film			
SECTION III - Physical/Chemical Characteristics			
Melting point	N/A	Specific Gravity	N/A
Boiling Point, Evaporation Rate	N/A	Vapor Pressure/Density	N/A
Solubility in Water	No data		
Appearance and Odor	Polyethyleneterephthalate film coated on one side there of with black ink.		

SECTION IV - Fire and Explosion Hazard Data				
Flash Point	N/A		Flammable Limits	LEL N/A UEL N/A
Extinguishing Media	Water mist, Foam, Dry powder, CO ₂ gas, others			
Special Fire Fighting Procedures	N/A			
Unusual Fire and Explosion Hazards	None			
SECTION V - Reactivity Data				
Stability	Unstable		Condition to Avoid N/A	
	Stable	X		
Incompatibility (Material to Avoid)	None			
Hazardous Decomposition or Byproducts	None			
Hazardous Polymerization	May Occur		Condition to Avoid N/A	
	Will Not Occur	X		
SECTION VI - Health Hazard Data				
Route(s) of Entry:	Inhalation?	Skin?	Ingestion?	
	No	Yes	Yes	
Health Hazards (Acute and Chronic)	No data available			
Carcinogenicity:	NTP?	IARC Monographs?	OSHA Regulated?	
	No	No	No	
Ames Test :	Negative			
Signs and Symptoms of Exposure	No data available			
Medical Conditions	Generally Aggravated by Exposure			
	No data available			
Emergency and First Aid Procedures	Wash away with soap and water an ink sticking to skin. If ink has contacted eye, wash it with enough water, then consult a doctor.			

SECTION VII - Precautions for Safe Handling and Use			
Steps to Be Taken in Case Material is Released or Spilled			
An inadvertently released or rewound ribbon should be wound again on the reel.			
Waste Disposal Method			
Dispose in accordance with local, state and federal regulations.			
Precautions to Be Taken in Handling and Storing			
Should be stored at dark and cold place.			
Other Precautions			
None			
SECTION VIII - Control Measures			
Respiratory Protection (Specify Type)		None	
Ventilation	Local Exhaust	N/A	Special N/A
	Mechanical (General)	N/A	Other N/A
Protective Gloves		Eye Protection	
N/A		N/A	
Other Protective Clothing or Equipment			
N/A			
Work/Hygienic Practices			
None			